





9T22





Battery consumption could be minimum by pulling out the stem






Time measurement

Accuracy


The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec





Assembly - Disassembly chart for Cal. 9T22





Assembly - Disassembly chart for Cal. 9T22

